

J1031 U.S. PRO
02/12/03

B.GOPINATH.

2/8




FIG.3




FIG.4

02/12/03
J10331 U.S. PRO

B.GOPINATH 3/8




FIG.5






FIG.6

02/12/03
JOTEA U.S. PTO

B.GOPINATH.




4/8



02/12/03
J1031 U.S. PTO

B. GOPINATH.





5 / 8



02/12/03
J1031 U.S. PTO

B.GOPINATH


6/8



02/12/03
1031 U.S. PTO

B.GOPINATH.

7/8



Section AA

FIG 15

See Fig 18
for continuation.





FIG 16

02/12/03
1031 U.S. PTO

B.GOPINATH.

8/8



END VIEW
DIRECTION 'C'

FIG. 17

See Fig. 16
for continuation




FIG. 18

02/12/03
J1031 U.S. PTO

B.GOPINATH.

Sheet 9




FIG 19



B.GOPINATH.

Sheet.10




FIG.20.




FIG.21

DEVICE.D.

B.GOPINATH.

Sheet 11.




FIG 22




FIG 23.

J1031 U.S. PTO
02/12/03

B. GO PINATH

1 / 8




FIG. 1




FIG.2